


# CLEANING PROCEDURE


## DYCEM® FLOATING MATS




For optimum performance, clean Dycem daily. Remove loose debris, then ensure the subfloor is clean and dry before cleaning the mat.



Clean the subfloor, agitating with a flat mop, in a vertical direction, and remove excess residue/liquid. Repeat horizontally.




Lift the mat and clean the underside with a 70/30 IPA wipe or approved cleaning solution. Allow it to dry before repositioning.



Return the mat to its original position, ensuring it lies flat. Apply Dycem-approved cleaning agent to the flat mop or use a spray bottle/pre-saturated wipe to cover the surface.



Using a flat mop, move it over the Dycem surface in a 'S'-shaped motion lifting the retained particulates. Work away from the controlled area.



Using a dry flat mop, repeat the 'S' motion to collect dirty liquid and dispose of per facility mandated SOPs. For heavily saturated mats, repeat cleaning steps 1-6 until the liquid removed is visibly clear.

### Tips & Advice

- Clean Dycem according to your facility's SOP.
- Use approved, low-residue cleaners suitable for critical environments.
- Use pre-saturated flat mop pads to prevent over-wetting.
- Avoid excess liquid near airflow and raised-floor systems.
- For spot cleaning, use a 70/30 isopropyl alcohol wipe or the supplied PVA sponge.
- Clean beneath loose-laid mats at least weekly and ensure the area is dry before replacing.
- Do not use bleach, abrasive products, stiff brushes, buffing, or polishing equipment. These may damage the surface and shorten the life of the Dycem.

Questions?  
[contact@dycem.com](mailto:contact@dycem.com)

